

**HHSRS Worked Examples from East Midlands
Standardisation Working Group
6 March 2008**



Example 15 – Food Safety

1950's two story semi detached house occupied by a single man. This is the kitchen ceiling and kitchen side board. Directly above the kitchen is the bathroom in which the pipe to the bath has been leaking.





HHSRS V2 SCORING SHEET

DWELLING House or flat **hse flat** HMO **Non HMO** Age of dwelling Pre 1920 20-45 **46-79** 80+

HAZARD & No **Food Safety** **16** Item/s **Collapsed ceiling in kitchen**

LIKELIHOOD **5** | 00 | 3200 | 1800 | 1000 | 560 | 320 | 180 | 100 | 56 | 32 | 18 | 10 | 6 | 3 | **2** | 1
 <4200 2400 1300 750 420 240 130 75 42 24 13 7.5 4 2.5 1.5>

Justification
Lack of cleansable work surface in kitchen
Disrepair to kitchen ceiling
Poor quality storage facilities
No tiled splashback

		<0.05	0.15	0.3	0.7	1.5	3	7	15	26	38>		
OUTCOMES Class I	1	0	0.1	0.2	0.5	1.0	2.2	4.6	10.0	21.5	31.6	46.4	Class IV
Class II		0	0.1	0.2	0.5	1.0	2.2	4.6	10.0	21.5	31.6	46.4	100-(I+II+III)
Class III		0	0.1	0.2	0.5	1.0	2.2	4.6	10.0	21.5	31.6	46.4	63.8
		<0.05	0.15	0.3	0.7	1.5	3	7	15	26	38>		

Justification
Due to the extremely poor conditions in the kitchen, any food poisoning caused is likely to be more severe than the average.

RATING **A** | B | C | D | E | F | G | H | I | J | Score (if calculated) **7359**

Enforcement Action:
The group decided that the most appropriate course of action would be to serve an Improvement notice requiring works to be carried out to the kitchen.